

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5040	DATE	October 28, 2021
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	<p>The rear door glass of some cars is not coated with an undercoating bond (primer) due to improper control of the bonding process. Therefore, as the adhesive strength of the glass is weak, if a vehicle with this condition is continuously used, the adhesive portion may be peeled off, which causes an abnormal noise. In the worst case, the glass may fall off from the vehicle, which may result in traffic interference.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5BD-S321V	HIJET	2021	859
3BD-S321V			
5BD-S331V			384
3BD-S331V			
3BA-S321G	ATRAI WAGON		64
3BA-S331G			29
5BD-S321B	SAMBAR		48
3BD-S321B			
5BD-S331B			43
3BD-S331B			
5BD-S321M	PIXIS VAN		105
3BD-S321M			
5BD-S331M		80	
3BD-S331M			
		TOTAL	1,612