

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~(~~ Import Vehicles)

CAMPAIGN No.	Gai-3309	DATE	2021/10/28
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	<p>On certain S-Class (223 platform) vehicles, a nozzle inside the suction jet pump in the fuel tank might not have been installed or fixed inside the pump according to specifications. If the nozzle were missing, this would lead to an early failure inside the production plant. If the nozzle was not fixed inside the pump according to specifications, the nozzle might detach within the suction jet pump. Subsequently, the fuel pressure necessary for driving under certain circumstances, such as reduced fuel level and full throttle operation, might not be reached. This might lead to sudden engine stalling without warning, which might increase the risk of a crash.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5AA-223063	S500 4MATIC	2021	24
5AA-223163			12
		TOTAL	36