

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5044	DATE	Nov. 4. 2021
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain rear underrun protection devices, due to insufficient design study of the ground height at the lower end of the rear surface structure of the vehicle body, some may exceed the maximum height. Therefore, these vehicles may fail to comply with the requirements of article 18-2 of the safety standard.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2DG-GDY231M	[HINO Dutro]	2021	4
2PG-GDY231M			
2DG-GDY281M	[HINO Dutro]	2021	6
2PG-GDY281M			
2DG-GDY231	[Toyota Dyna]	2021	122
2PG-GDY231			
2DG-GDY281		2021	92
2PG-GDY281			
3BF-TRY230		2021	38
		TOTAL	262