

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5051	DATE	November 11. 2021
MANUFACTURER	YANMAR AGRIBUSINESS CO.,LTD.		
DESCRIPTION OF DEFECT	<p>In the foot accel of an agricultural tractor, the foot accel arm may tilt due to the improper assembly direction of the return spring. Therefore, the frictional force of the foot accel arm increases and the return of the foot accel becomes worse. In the worst case, even if the foot is released from the state where the foot accel is depressed, the engine rotation may not decrease to the idling rotation and It is necessary to operate the brake.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
-	「YT228」	2018~2021	754	
		2018~2021	941	
	「YT232」	2020~2021	46	
		2018~2021	146	
-	[YT233A]	2020~2021	385	
TOTAL			2,272	