

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5048	D A T E	Nov.19. 2021
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	Since the electric parking brake control program is inappropriate in the VDC (Vehicle Dynamics Control) unit, if vehicle vibration enters while the electric parking brake is operating, the sensor may react hypersensitivity and misrepresent as driving. Therefore, the warning light may be turned on, and the electric parking brake may not be able to be released.		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
4BA-VN5	「Levorg」	2020~2021	18,517
TOTAL			18,517