

Form No. 4: Summary of Recall Campaign in English (Related to Article 2)

Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

Campaign No.	Gai-3319	Date	Nov.30, 2021
Manufacturer	Jaguar Land Rover Limited Japanese Importer: Jaguar Land Rover Japan Limited		
Description of defect	The 'AUTO' text is not illuminated with indicator when high beam automatically turns on while auto high beam or adaptive driving are enabled. Retailers / Dealers will update the vehicles with the latest software.		

Type	Commercial name	Model year recalled	Number of vehicles
7BA-DC5SC	F-PACE SVR	2019	1
CBA-DC3VA	F-PACE	2019-2020	2
DBA-DC2XB		2019-2020	4
LDA-DC2NA		2019-2020	4
5LA-LG2YE	Range Rover	2019-2020	11
5LA-LGL2YE		2020	1
5LA-LW2YC	Range Rover Sport	2020	20
7AA-LW3UD		2020	91
7BA-LY5SC	Range Rover Velar SVA-D	2020	1
ABA-LG3SB	Range Rover	2018-2019	5
ABA-LG5SA		2019-2020	32
ABA-LGL5SC		2020	5
ABA-LR3VA	Discovery	2018-2019	9
ABA-LW3SA	Range Rover Sport	2018-2019	4
ABA-LW5SA		2018-2020	37
CBA-LY3VA	Range Rover Velar	2018-2020	16
DBA-LY2XAB		2018-2020	3
DBA-LY2XCB		2018-2020	17

(JIS A4 size)

LDA-LG3KD	Range Rover	2018-2020	88
LDA-LR3KA	Discovery	2018-2020	49
LDA-LW3KB	Range Rover Sport	2018-2020	189
LDA-LY2NA	Range Rover Velar	2018-2020	30
		Total	619

(JIS A4 size)