

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

| | | | |
|-----------------------|--|------|------------------|
| CAMPAIGN No. | 5058 | DATE | December 2, 2021 |
| MANUFACTURER | Mazda Motor Corporation | | |
| DESCRIPTION OF DEFECT | On certain spare tire clamps for double-tire sold for the service parts in the field, due to improper part storage management, some parts, whose specification is not correct, were distributed. Therefore, if the parts are equipped, the tightened bolt may loosen, causing the spare tires to fall off the carrier. As a result, this may obstruct the traffic. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|-----------------------------------|------------------|-------------------------|-------------------|
| ABF-SKP2T | Mazda 「BONGO」 | 2012-2015 | 4 |
| ABF-SKP2L | | 2012 | 1 |
| ADF-SKF2T | | 2010 | 1 |
| KR-SKF2L | | 2007 | 1 |
| ABF-SK82T TC-SK82T GC-SK82T | | 2001-2010 | 6 |
| TC-SK82L | | 2006 | 1 |
| GA-SE88M | | 1996 | 1 |
| KF-SK22T | | 2000 | 1 |
| KB-SD29T | | Mazda 「BONGO BRAUNY」 | 1997 |
| U-SD2AM | 1991 | | 1 |
| | | Total | 18 |