

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3323	DATE	Dec. 2 2021
MANUFACTURER	Mercedes-Benz (Japanese importer : Mitsubishi Fuso Truck and Bus Corporation)		
DESCRIPTION OF DEFECT	On some articulated buses, some of the piston mounting bolts for the air springs on the axles are not tightened to the specified torque. Therefore, the mounting bolts may loosen during use and the pistons may fall off.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Unclear model	「Citaro-G」	2020~2020	5
		TOTAL	5