VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

	Domestic/Import Vehicles		
CAMPAIGN No.	5062	DATE	December 7, 2021
MANUFACTURER	Mitsubishi Logisnext Co., Ltd		
DESCRIPTION OF DEFECT	Due to improper welding of the members that fix the left and right rear wheel brakes to the rear axle shaft, either of the members may come off from the rear axle shaft when continued operation. Therefore, the braking distance may be increased by the one rear wheel brake and the regenerative brake of the front wheel.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
471AB	「ELETRUCK」	2020 2021	20
	<u>.</u>	TOTAL	20

Domestic/Import Vehicles