

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3328	DATE	December 8, 2021
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	Airbag may not deploy properly and lead to an increased risk of injury. The airbag inflator is replaced.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GF-4BAPRF	Audi A6 2.8 quattro	2000-2001	83
GF-4BAPSF	Audi A6 2.4 quattro	2000-2001	30
GF-4BAQJF	Audi S6	2001	17
GF-4BAZAF	Audi A6 2.7T quattro	2001	18
GF-4DAQF	Audi A8 quattro 4.2	2000	10
GF-8DAGBF	Audi S4	2000-2001	28
GF-8DAPS	Audi A4 2.4	2001	23
GF-8DAPSF	Audi A4 2.4 quattro	2000-2001	122
GF-8DAPT	Audi A4 1.8	2001	120
GF-8DAPUF	Audi A4 1.8T quattro	2001	17
GF-8NAPXF	Audi TT Coupé 1.8T quattro / Audi TT Roadster 1.8T quattro	2000	336
		Total	804