VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3334	Date	December 13, 2021	
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)			
DESCRIPTION OF DEFECT	In a dash panel, it is possible that insufficient strength of the net due to improper weaving for the design breakage point for the discharge of the passenger airbag has been installed. Therefore, in the event of an airbag deployment at very cold temperatures (-15°) and a correspondingly cooled dash panel the broken piece from the dash panel could damage the windscreen. In the worst case, the airbag may be incompletely inflated and there is a risk of injury.			

ТҮРЕ	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
3BA-AWDKL	Polo 1.0/70kW	MY2021	39
3BA-AWDAD	Polo 1.5/110kW	MY2021	4
3BA-AWCZP	Polo GTI2.0/147kW	MY2021	3
		Total	46