

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5 0 7 3	DATE	December 14, 2021
MANUFACTURER	SAKAI HEAVY INDUSTRIES, LTD.		
DESCRIPTION OF DEFECT	In the front axle of the grader, the durability of the hub shaft is insufficient, so the hub shaft may crack when turning at high speed. Therefore, if the vehicle is used as it is, cracks will develop, and in the worst case, the hub shaft may break and the tire may fall off from the vehicle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JDS-MER10	「ER552F」	2005 — 2013	129
1ER12	「ER552F-1」	2011 — 2016	100
YDS-1ER13	「ER555F」	2017 — 2021	112
		TOTAL	341

[Caution] The range of the chassis numbers of the vehicles subject to recall may include vehicles that are not subject to recall.