

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai – 3313	DATE	17 December, 2021
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	There is a possibility that carrier side sections that do not meet the required specifications due to a manufacturing error were installed on the rear axle of the affected vehicles during a certain time period. If this is the case, one or both wishbone mounts on the carrier side section can break over the service life of the vehicle. If both mounts break, this would result in impaired wheel guidance. A potential loss of control of the vehicle cannot be ruled out if this happens.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-981MA122	718 Cayman	2014	80
		2015	152
	718 Boxster	2013	274
		2014	45
		2015	143
ABA-981MA123	718 Cayman S	2014	54
		2015	59
	718 Cayman GTS	2015	10
	718 Boxster S	2013	116
		2014	14
		2015	50
	718 Boxster GTS	2015	3
		Total	1000