

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3339	DATE	24, Dec, 2021
MANUFACTURER	Automobili Lamborghini SpA (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	The screws on the connection of the heat exchanger oil lines may not have been properly torqued during the assembly process. Confirmation of the correct mounting of the assembly cannot be ensured. Should the mounting assembly not meet the torque specification, the oil lines could detach, and leak oil, which could potentially contact hot components increasing the risk of a fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
7BA-47L539	Aventador LP740-4	2021	1