

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN NO.	5 0 8 3	DATE	January.17. 2022
MANUFACTURER	NICHIGO CORPORATION		
DESCRIPTION OF DEFECT	<p>Traveling device of rotary snowplow, Some hub bolts may break due to insufficient strength of the wheel mounting hub bolts. Therefore, the hub bolt and hub nut fall off in the brake drum, and if you continue to use it as it is, the hub bolt and hub nut will get caught between the brake drum and the brake shoe, and in the worst case, the tire rotation will stop and you will not be able to drive, etc. There is a risk of obstructing traffic.</p>		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UDS-R03D	HTR306	2013~2017 R03D-0002~ R03D-0321	318
YDS-R03E	HTR308	2016~2018 R03E-0002~ R03E-0114	111
YDS-R03F	HTR308A	2018~2021 R03F-0002~ R03F-0260	247
R06F	HTR410	2021 R06F-0001~ R06F-0003	3
		TOTAL	679

【Notes】 The scope of the chassis number of the recalled vehicles, there is a case where