

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3343	Date	January 28, 2022
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	In a driver airbag inflator, the propellant can deteriorate because of high humidity environment and temperature fluctuations. As a result, container of the inflator may rupture when airbag deploy.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-16CBZ	VW The Beetle 1.2/77kW	MY2012-MY2014	18,048
DBA-16CBZK	VW The Beetle Cabriolet 1.2	MY2013-MY2014	1,012
ABA-16CPL	VW The Beetle 2.0T	MY2014	1,054
		Total	20,114