

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai – 3344	DATE	31 January, 2022
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	Based on findings from internal quality inspections, it was discovered that on the affected vehicles, individual indicator lights in the instrument cluster are not displayed within the 'bulb check' after the ignition is switched on. Due to the missing warning icons in the 'bulb check', the vehicles do not fully comply with certain legal requirements.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
3BA-G2ML1	Panamera	2021	211	
3BA-G2ML2	Panamera 4		95	
3BA-G2MR	Panamera GTS		191	
3BA-G2MS	Panamera Turbo S		29	
3LA-G2MM	Panamera 4 E-Hybrid		55	
3LA-G2MP	Panamera 4S E-Hybrid		36	
3LA-G2MT	Panamera Turbo S E-Hybrid		8	
7BA-G2NL2X	Panamera 4		4	
3BA-992NA1	911 Carrera		2022	131
	911 Carrera S			22
3BA-992NA2	Carrera 4	14		
	Carrera 4 S	8		
	911 Targa 4	22		
	911 Targa 4S	13		
3BA-992NE	911 Turbo	14		
	911 Turbo S	46		
7BA-992ME	911 Turbo S	1		
7BA-992NC1	911 Carrera GTS	1		
7BA-992NC2	911 Carrera 4 GTS	1		
7BA-992NG	911 GT3	26		
3BA-E3NA	Cayenne	41		
3BA-E3NAA	Cayenne	9		
3BA-E3NB	Cayenne S	1		
3BA-E3NBA	Cayenne S	2		

3BA-E3NCA	Cayenne Turbo		1
3BA-E3NI	Cayenne GTS		6
3BA-E3NIA	Cayenne GTS		7
3LA-E3NF	Cayenne e-hybrid		5
3LA-E3NFA	Cayenne e-hybrid		3
ZAA-J1NA1	Taycan		4
ZAA-J1NA1C	Taycan		3
ZAA-J1NA2	Taycan 4		1
ZAA-J1ND	Taycan Turbo S		1
		<b>Total</b>	<b>1012</b>