

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5101	DATE	February 14, 2022
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	<p>For forklifts with pneumatic double tires on the front wheel, the side ring may come off the wheel due to improper shape of the side ring and lock ring that make up the wheel. The continuous use may cause the tire to protrude from the wheel. In the worst case, the tire tube may come into contact with the end of the lock ring of the wheel and make a hole, leading to a flat tire.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAF-M299	FE30-2	2021	5
		TOTAL	5