

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5099	DATE	February 17,2021
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	With regard to some turbochargers on the affected vehicles, due to improper specifications of the seal ring at the connection section of the housings, the seal may fail while in use depending on variations in accuracy of the component parts, and this may cause an exhaust gas leakage from the section where the seal becomes inappropriate.		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-CV1W	「DELICA」	2012~2014	11,821
		TOTAL	11,821