

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5103	DATE	Feb.24 2022
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some 4WD light-duty trucks equipped with an electric parking brake, the electric parking brake cable may interfere with the passenger seat bracket due to improper routing of the cable. Therefore, the outer casing of the cable may be scuffed due to the vibration of the vehicle. In the worst case, the cable may break during parking and the vehicle may start moving without permission, resulting in a collision accident or the like.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FDA50	「FUSO CANTER」	2019~2021	11
2PG-FDA60		2019~2020	26
2PG-FGA50		2019~2021	7
2RG-FDA20		2019~2021	110
2RG-FGA20		2019~2021	33
2RG-FGA50		2020	1
TPG-FDA20		2018~2019	38
TPG-FDA50		2018~2019	7
TPG-FDA60		2018~2019	7
TPG-FGA20		2018	1
TPG-FGA50		2018~2019	3
2RG-FGA5W		2019	1
2RG-FGA5Y		2020	1
		TOTAL	246