

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5104	DATE	Feb.24 2022
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some AMT (automated manual transmission) light-duty trucks equipped with an easy access system, the easy access system wiring may interfere with the DC/DC converter bracket due to improper routing of the wiring. Therefore, the wiring may be short-circuited. In the worst case, the engine may stall during driving, or the engine may not start after turning the ignition key to the off position.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2RG-FEB50	「FUSO CANTER」	2021~2021	7
2RG-FEB80		2021~2021	6
2RG-FEB20		2021~2021	2
2RG-FBA20		2021~2021	22
2RG-FBA30		2021	1
2RG-FBA60		2021	1
2RG-FBAV0		2021~2021	7
2RG-FDA20		2021~2021	3
2RG-FDA50		2021~2021	2
2RG-FEA20		2020~2021	11
2RG-FEA80		2020	1
2RG-FEAV0		2021~2021	12
2RG-FGA20		2021~2021	5
2RG-FGA50		2020	1
2TG-FBA00		2021~2021	14
		TOTAL	95