

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	4884	DATE	January 28, 2021
MANUFACTURE	TOYOTA INDUSTRIES CORPORATION		
DESCRIPTION OF DEFECT	With the electronic forklift vehicles, there are cases where certain impurity is mixed in the battery electrode pole seal during production, and this may lead to electrode pole corrosion. Continuous usage under such condition, may lead to electrode pole damage and cut the power to the vehicle, disabling the operation of the vehicle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAF-8FBE18	TOYOTA GENEEO-E	2018	11
ZAF-8FBL18	TOYOTA GENEEO-B	2018	72
ZAF-8FBL25		2018	3
ZAF-8FB18		2018	1
ZAF-8FB25		2018	2
		TOTAL	