

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4887	DATE	February 4, 2021
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Noise label containing incorrect values in the noise test condition and acceleration noise value columns may have been affixed to the vehicle body due to noise label stocktaking errors. This constitutes a nonconformity to technical requirements of the Regulation No. 41.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BK-MC51	「CBR250RR」	2020	1
		TOTAL	1