

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

| | | | |
|-----------------------|---|---------------------|-------------------|
| CAMPAIGN No. | 4 8 9 2 | DATE | February 15, 2021 |
| MANUFACTURER | ISEKI & CO., LTD. | | |
| DESCRIPTION OF DEFECT | Rolling and rear arms of the combine harvester controlling the attitude are broken because of the lack of strength caused by design fault, which may result in loss of attitude control when extreme loads are applied to them. | | |
| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
| YDR-H173 | 「HJ6115」 | 2018 | 65 |
| YDR-H174 | 「HJ5101」 | 2018 | 60 |
| | | TOTAL | 125 |