

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	4 8 9 3	DATE	February 15, 2021
MANUFACTURER	ISEKI & CO., LTD.		
DESCRIPTION OF DEFECT	Combine harvester accumulates dust around the SCR of engine because there is a path way due to the structural design failue. The dust may be fired at worst when the heat is transmitted from SCR in which temperature is very high.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDR-H178	「HJ7130」	2018~2020	21
YDR-H178	「HJ6130」	2018~2020	302
		TOTAL	323