

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-3170	DATE	Feb 17 2021
MANUFACTURE	FCA US LLC (Japanese Importer : Fiat Chrysler Automobiles Japan Ltd. )		
DESCRIPTION OF DEFECT	The fuel pump relay that was installed as a recall remedy may be susceptible to silicon contamination of the relay contacts, that can cause the relay to fail. A fuel pump relay failure can result in a no-start condition or an engine stall condition if the vehicle is running.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-WK36	「Grand Cherokee」	2011-2013	1,763
ABA-WK36A	「Grand Cherokee」	2011-2013	1,155
ABA-WK57A	「Grand Cherokee」	2012-2013	140
Unknown	「Grand Cherokee」	2012-2013	170
		TOTAL	3,228