

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3167	Date	February18, 2021
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	Due to improper material of the bulb holder, it may deform by the heat of the bulbs. As a result, the contact failure may occur and the warning lamp turn on then brake lamp/tail lamp may not light in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-AUCHP	Golf Variant 1.4L	MY2014-2017	11,163
DBA-AUCJZ	Golf Variant 1.2L	MY2014-2017	10,344
ABA-AUCJXF	Golf R Variant 2.0L	MY2015-2017	1,006
ABA-AUCJSF	Golf Alltrack 1.8L	MY2015-2017	2,110
DBA-1TCZD	Golf Touran 1.4L	MY2016-2019	5,667
LDA-1TDFG	Golf Touran TDI	MY2018-2019	170
		Total	30,460