VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3174	Date	February 18, 2021	
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)			
DESCRIPTION OF DEFECT	In the suction jet pump with fuel gauge attached to the fuel tank, the pump may tilt during the process of use due to improper assembly instructions at the time of manufacture. As a result, the remaining amount of fuel cannot be detected correctly and it will be displayed more than it actually is, and in the worst case, there is a risk of engine stalling due to running out of fuel while driving.			

ТҮРЕ	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
ABA-3HDJHF	Arteon 2.0/206kW	MY2018-MY2019	3,408
LDA-3CDFCF	Passat Alltrack TDI/140kW	MY2018-MY2019	979
		Total	4,387