

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-3177	DATE	2021/2/25
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	<p>On certain CLA vehicles (118 platform) the right handle (outer side) for attaching the child seat to the ISOFIX bracket might be missing on the right rear seat.</p> <p>In this case, the child seat could not be secured in accordance with the legal requirements. In the event of a crash, the restraining function of the lower ISOFIX anchorage system would not be given.</p> <p>This would increase the risk of injury of a child in the not properly secured child seat. Moreover, legal requirements might not be met.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5BA-118384M	CLA180	2021	3
5BA-118684M	CLA180 Shooting Brake		1
3DA-118312M	CLA200d		9
3DA-118612M	CLA200d Shoot Brake		4
		TOTAL	17