

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4920	DATE	Apr. 1, 2021
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>Due to the improper program in the engine controller for the intake air volume control at engine idling status, the intake air volume may become insufficient while the vehicle is at stand still in D range.</p> <p>The above may result in the dropping of the engine idling rpm and the engine may stall in the worst case.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES	NOTE
5AA-MR92S	HUSTLER	2019~2020	48,127	
5AA-MH95S	WAGON R	2020	41,756	
5AA-MS92S	FLAIR CROSSOVER		3,658	
5AA-MJ95S	FLAIR		5,046	
		TOTAL	98,587	