

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3199	DATE	April. 5 <sup>th</sup> , 2021
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Fuel components respectively fuel additives which do not meet the Japanese fuel specification can be deposited in the fuel pump located into the fuel tank. The deposits can lead to a sporadic blocking of the fuel pump after long journey and high temperatures. This can cause a non-start condition of the engine when using the auto-start-stop function. In the worst case, the engine can switch off while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-WY20	BMW X3 xDrive 20d	2012 - 2017	10,823
		TOTAL	10,823