

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4 9 1 6	DATE	April 8, 2021
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On the passenger airbag, air bag cushion may not be folded correctly due to inappropriate folding method of air bag. Therefore, the seams may burst open and airbag may not deploy correctly when the airbag is activated in a collision, resulting in the deterioration of the occupant protective performance.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5AA-DREJ3P	Mazda 「MX – 3 0」	2020	2,146
ZAA-DRH3P			7
		Total	2,153