

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Imported Vehicles

CAMPAIGN No.	gai-3204	DATE	April 13, 2021
MANUFACTURER	RENAULT SAS (Japanese Importer : Renault Japon Co., Ltd.)		
DESCRIPTION OF DEFECT	Due to inappropriate design of the clearance between impeller and the upper-cap of the in-tank fuel pump, fuel temperature rise may cause the impeller to interfere with the upper-cap. As a result, the fuel pump motor will malfunction. At the worst case, there will be a risk of stalling while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
7BA-BJAH5H	LUTECIA	2020	159
		TOTAL	159