

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4890	DATE	April 16, 2021
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	Due to improper design of the cover for shielding the high temperature part of the DPF muffler, straw debris may accumulate around and contact with the exhaust pipe of the DPF muffler. It may set accumulated straw debris on fire during the DPF regeneration process, and turn into the vehicle fire in the worst case.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
XDN-C519	「ER575」	2013~2017	422
YDN-C521		2017~2018	403
WDP-C518	「ER590」	2013~2017	661
WDP-C613	「ER6100」	2013~2017	767
WDR-C612	「ER6120」	2013~2017	1,473