

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3207	DATE	April 19 th , 2021
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Tires out of specification with too long heating in the vulcanization process were delivered from the supplier and equipped on BMW vehicles. Thus, insufficient elasticity and durability of the tire may lead to sudden pressure loss or separation of the tire in worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-CV30A	「BMW X5 xDrive 35d」	2020	4
		TOTAL	4