

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3205	DATE	22th, Apr, 2021
MANUFACTURER	Automobili Lamborghini SpA (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	Loss of torque of engine hood hinge screws may result in an unlatched hood. This could increase the likelihood that with a combination of factors such as high speed under strong vertical and longitudinal acceleration, the wind force is sufficient to inadvertently flip open the hood.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-47L541	Aventador SVJ	2019 - 2020	139
7BA-47L541	Aventador SVJ	2019 - 2021	10