

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3212	DATE	April. 26 th , 2021
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to the plastic coolant pipe manufacturing defect, it may come into contact with the belt pulley of the air conditioning compressor. The contact between the coolant pipe and the belt pulley can result in chafing and associated leakage of the coolant pipe.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-5V20	BMW 320d xDrive	2020 - 2021	567
		TOTAL	567