

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import~~ Vehicles

CAMPAIGN No.	4951	DATE	April 28, 2021	
MANUFACTURER	UD Trucks Corporation			
DESCRIPTION OF DEFECT	<p>With regard to Heavy-Duty Tractors, due to insufficient fastening torque for the bolts/nuts to secure the spare tire carrier to the vehicle, some of the vehicles may have decreased fastening torque. Thus, if the vehicle is operated continuously in this condition, the bolts/nuts might become loose due to vibration occurring during vehicle operation. In the worst case, the bolt/nut might come off after which the spare tire may detach along with the spare tire carrier and may have a risk of interfering with other transportation.</p>			
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-GK5AAB	Quon	2020 - 2021	2	
2PG-GK5AAD	Quon	2020 - 2021	21	
2PG-GK5AAE 2PG-GK5AAEKai	Quon	2020 - 2021	3	
		TOTAL	26	