

## VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4948	DATE	April 28, 2021
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	The springs of the accelerator pedal that install on forklifts may not have enough strength. The continuous use can break the springs. In the worst case, the accelerator pedal can't return to the normal position and may keep full accelerator. In that case, the forklift can be stopped by using brake and may not be able to travel even if return on key switch after turning off key switch.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
M190		2002-2005	589
M190T		2005-2006	51
ZAF-M190T		2006	151
M193		2003-2005	69
M193T		2006	8
ZAF-M193T	「FB20」 「FB25」	2006-2011	153
ZAF-M193TK	「FB20」 「FB25」	2011-2014	100
M194		2005	2
ZAF-M194T		2006-2010	4
M195		2004	1
ZAF-SM236	「FB09H」 「FB10」 「FB14」 「FB15」 「FB15HB」	2006-2011	817
ZAF-SM236K	「FB09H」 「FB10」 「FB14」 「FB15」 「FB15HB」 「FE15」	2011-2020	1762
ZAF-M237	「FB18」 「FB20A」	2007	1
ZAF-SM237	「FB18」 「FB18HB」 「FB20A」 「FB20AHB」	2006-2011	204
ZAF-SM237K	「FB18」 「FB18HB」 「FB20A」 「FB20AHB」 「FE18」	2011-2020	493

ZAF-M238	「FB09ML」「FB10ML」 「FB13ML」	2006-2011	53
ZAF-M238K	「FB09ML」「FB10ML」 「FB13ML」	2011-2020	100
ZAF-M239	「FB15ML」	2007-2011	79
ZAF-M239K	「FB15ML」	2011-2020	135
ZAF-SM243	「FB15G」「FB18G」 「FB20AG」	2007-2010	6
ZAF-M254	「FB20HB」「FB25HB」	2008-2011	8
ZAF-M254K	「FB20HB」「FB25HB」	2011-2013	6
		TOTAL	4,792