

第4号様式(英文リコール概要書) (第2関係)

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

| | | | |
|-----------------------|--|------|----------|
| CAMPAIGN No. | 外-3376 | DATE | 2022/4/1 |
| MANUFACTURER | MASSEY FERGUSON (Japanese Importer :MSK Farm Machinery Corporation CEO Saito Yoshiyuki) | | |
| DESCRIPTION OF DEFECT | In the braking devices of agricultural tractor, air is mixed into the hydraulic circuit due to inadequate design of the hydraulic circuit. Therefore, if the vehicle is used as it is, the braking performance may deteriorate. We will add a check valve to the brake hydraulic circuit of all vehicles. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|------------|-----------------|---------------------|-------------------|
| YDS-SU74A2 | MF7726S-4V | 2018~2019 | 8 |
| | MF7726-4CVT | 2016~2018 | 21 |
| | MF7724S-4V | 2018~2020 | 6 |
| | MF7724-4CVT | 2016~2018 | 13 |
| | MF7722S-4V | 2018~2021 | 14 |
| | MF7722-4CVT | 2016~2018 | 10 |
| YDS-SU66A2 | MF7720S-4V | 2018~2020 | 6 |
| | MF7720-4CVT | 2016~2018 | 19 |
| | MF7718S-4V | 2018~2019 | 14 |
| | MF7718-4CVT | 2016~2018 | 32 |
| YDS-SU49A2 | MF6718SS-4V | 2018~2019 | 10 |
| | MF6718S-4V | 2018 | 2 |
| | MF6716SS-4V | 2018~2019 | 7 |
| | MF6716S-4V | 2018 | 1 |
| YDR-SU49A2 | MF6714SS-4V | 2018~2019 | 8 |
| | MF6714S-4V | 2018 | 1 |
| | MF6713SS-4V | 2018~2019 | 12 |
| | MF6713S-4V | 2018 | 2 |
| | | TOTAL | 186 |