

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5127	DATE	March 30, 2022
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	<p>For the oil filter case used in the brake hydraulic circuit of the shovel loader and motor grader, the durability does not satisfy the standards because of improper manufacturing method, and there is a possibility that hydraulic oil leaks from the oil filter case when high pressure is continuously applied.</p> <p>As for the motor grader, since the same oil filter case is used in the steering hydraulic circuit and the differential lock hydraulic circuit, there is a possibility that the hydraulic oil leaks from the oil filter case when a high pressure is continuously applied.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDP-WA138	WA100-8	2021	85
YDP-WA138	WA150-8	2021	26
YDR-WA137	WA200-8	2021	25
YDR-WA136	WA270-8	2021	7
YDR-WA135	WA320-8	2021	22
YDR-GD035	GD405-7	2021	26
YDS-GD032	GD675-6	2021	12
TOTAL			203