

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5117	DATE	Mar. 23. 2022
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain passenger seat side mirrors of light duty trucks, mirror stays shorter than the regular parts are installed due to the inappropriate design instructions. Therefore, these vehicles may fail to comply with the requirements of Article 44 of the Safety Standard, "Rear Visibility" .		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2DG-GDY231M	[HINO Dutro]	2021	1
2PG-GDY281M		2021	1
2DG-GDY231 2PG-GDY231	[Toyota Dyna]	2021~2022	66
2DG-GDY281 2PG-GDY281		2021~2022	60
3BF-TRY230		2021~2022	77
		TOTAL	205