## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic / Import Vehicles

CAMPAIGN No.	外 3362	DATE	March 22 <sup>th</sup> , 2022	
MANUFACTURE	Bimota S.p.a			
	(Japanese Importer : CC	ORSE Corporation	)	
DESCRIPTION OF DEFECT	On eligible units of the models listed below the oil pressure relief valve may fail resulting in low oil pressure. This could lead to the oil pressure warning light illuminating and, in the worst case cause the engine to stop.  To overcome this problem Bimota has initiated a recall campaign to replace the oil pressure relief valve.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BTH2	TESI H2	2020	ZRPBTH201ERL000003 ~ ZRPBTH201ERL000250
		TOTAL	23