

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-3345	DATE	Mar. 18, 2022
MANUFACTURE	Harley-Davidson Motor Company (Japanese Importer : Harley-Davidson Japan K.K. )		
DESCRIPTION OF DEFECT	The embedded nut for fixing the plastic grab bar at the rear of the vehicle is improperly assembled, and some of them are not assembled correctly with the required strength. Therefore, when a large load is applied, such as when holding the grab bar handle and applying the center stand, the embedded nut may come off, causing the grab bar to crack, and in the worst case, a passenger may be injured by the crack when grasping the grab bar.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BL-RAS	PAN AMERICA S	2021	727
8BL-RAS	PAN AMERICA	2021	145
		TOTAL	872