

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-3360	DATE	Mar. 18, 2022
MANUFACTURE	Harley-Davidson Motor Company (Japanese Importer : Harley-Davidson Japan K.K.)		
DESCRIPTION OF DEFECT	In instrument modules, if the ignition is turned on when the internal temperature is below 0° C due to improper programming, an error message may appear on the screen and then nothing will be displayed. As a result, the speedometer and neutral lamp will not be displayed.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BL-RAS	PAN AMERICA S	2021	728
8BL-RAS	PAN AMERICA	2021	145
8BL-RH4	SPORTSTER S	2021	886
		TOTAL	1759