

第4号様式(英文リコール概要書) (第2関係)

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	5110	DATE	2022/3/4
MANUFACTURER	NIPPON TREX CO., LTD. 350 Minamiyamashinden, Ina-cho, Toyokawa city, Aichi prefecture, Japan		
DESCRIPTION OF DEFECT	Regarding the spring seat of the axle section of a van trailer with a dolly, some of the shock absorber mounting bolt's strength is insufficient due to inappropriate welding. Therefore, the shock absorber may crack under the load of driving, and in the worst case, the shock absorber may detach from the axle spring seat, resulting in loss of driving stability and inability to drive.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TFA137AA	-	2019	6
TFA137AB	-	2019~2020	16
TFA137AC	-	2020	2
TOTAL			24