

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	5111	DATE	2022/3/4
MANUFACTURER	NIPPON TREX CO., LTD. 350 Minamiyamashinden, Ina-cho, Toyokawa city, Aichi prefecture, Japan		
DESCRIPTION OF DEFECT	Regarding some of the relay emergency valve mounting area of the van trailer with dolly, due to insufficient strength, the mounting socket mounting area on the reservoir port side and the pipe joint on the service port side may crack due to vibration during driving. This causes damage to these parts and air leaks. In the worst case, the emergency brake may be activated and the vehicle may become unable to drive.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TFA137AA	-	2019	6
TFA137AB	-	2019~2020	16
TFA137AC	-	2020	2
TFA235AA	-	2021	1
TFW234AA	-	2019~2020	3
TFW235AA	-	2021	1
TFW237AA	-	2021	12
TFW234AB	-	2022	2
TFW237AB	-	2022	2
TOTAL			45