

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	5108	DATE	Mar. 3, 2022
MANUFACTURER	Kawasaki Motors, Ltd.		
DESCRIPTION OF DEFECT	The harness holding the vehicle's horn in place may break due to engine vibration generated by the engine certain rpm ranges. This could lead to horn malfunction.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Notes
2BL-EJ800B	「W800 STREET」 「W800 CAFE」 「W800」 「MEGURO K3」	2019～2021	2,818	
8BL-EJ800B	「W800 STREET」 「W800 CAFE」 「W800」 「MEGURO K3」	2022	1,161	
TOTAL			3,979	