

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5109	DATE	Mar. 3 2022
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some MY2019 heavy-duty trucks equipped with a 6R20 engine, fault diagnosis will not be performed correctly because the program of the aftertreatment control module (ACM) is incorrect.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-FV70HX	「FUSO SUPER GREAT」	2019~2021	138
2KG-FV70HYP		2019~2021	74
2KG-FV70HWP		2019~2021	23
2PG-FS70HZ		2019~2021	287
2PG-FS74HZ		2019~2021	495
2PG-FS75HZ		2019~2020	5
2PG-FU70HY		2019~2021	22
2PG-FU74HZ		2019~2021	183
2PG-FV70HX		2019~2021	943
2PG-FV70HY		2019~2021	137
2PG-FV70HZ		2019~2021	218
			TOTAL