

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

| | | | |
|-----------------------|--|------|-----------|
| CAMPAIGN No. | Gai-3398 | DATE | 2022/4/27 |
| MANUFACTURE | Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.) | | |
| DESCRIPTION OF DEFECT | <p>On certain S-Class (223 platform) vehicles, the airbag control unit might not have been bolted according to specifications.</p> <p>In this case, the airbag control unit might detect incorrect acceleration values while driving. In this connection, an unintended deployment of the restraint systems in the vehicle cannot be ruled out completely.</p> <p>Furthermore, in case of a crash, incorrect acceleration values might be detected. In consequence, the restraint systems might not be activated as specified.</p> <p>Depending on the scenario, the risk of a crash or injury would be increased. In addition, local legal requirements might not be met.</p> | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|------------|-----------------|---------------------|-------------------|
| 3DA-223033 | S400d 4MATIC | 2021 | 33 |
| 3DA-223133 | | | 2 |
| 5AA-223063 | S500 4MATIC | | 66 |
| 5AA-223163 | | | 57 |
| | | TOTAL | 158 |